

Annual Inspection

Hawesbury Play Area,
High Street,
Hawkesbury,
GL9 1AU

carried out by :-



Chartered Institute of
Environmental Health
Training Account



www.rynat.demon.co.uk



jbc@rynat.demon.co.uk



Annual Inspection



John Bedford Clark DipSm MIIRSM
3, Holly Terrace,
Balby,
Doncaster,
DN4 8RE
www.rynat.demon.co.uk

Site Address :- Hawesbury Play Area, High Street,
Hawkesbury, GL9 1AU

Grading Codes : **Date:** **Time : 15.00**
14 / 03 / 23

A) Satisfactory B) Monitor C) Work required to rectify D) Urgent Attention Required within 7 days

N 51 ° 34 ' 55 "
W 02 ° 19 ' 22 "

Equipment Inspected :-	Image	Grading Code				Conforms to BS EN 1176	
		A	B	C	D	Yes	No
General Well viewed from village hall & car park. Junior & Toddler area fenced and separated. Senior external.		√				N/A	
Signage in place, 2 benches, 3 gates & a bin – gate to adjust and threads on signage to cut back Potential trip point to address at gate.				√		N/A	
Huck Trampoline 20.02.126 The equipment is installed in a safe manner onto wet pour safety surfacing. Safe for use		√				√	
Fahr Formula One Racing Panel The equipment is installed in a safe manner. Safe for use		√				√	
Inspected by : J B Clark		Sheet - 1 of 9					



Annual Inspection








John Bedford Clark DipSm MIIRSM
3, Holly Terrace,
Balby,
Doncaster,
DN4 8RE
www.rynat.demon.co.uk

Site Address :- Hawesbury Play Area, High Street,
Hawkesbury, GL9 1AU

Grading Codes :	Date: 14 / 03 / 23	Time : 15.00
------------------------	------------------------------	---------------------

A) Satisfactory	B) Monitor	C) Work required to rectify	D) Urgent Attention Required within 7 days
-----------------	------------	-----------------------------	--

N 51 ° 34 ' 55 "
W 02 ° 19 ' 22 "

Equipment Inspected :-		Grading Code				Conforms to BS EN 1176	
		A	B	C	D	Yes	No
Playdale Train PLT-2019 The equipment is installed in a safe manner onto wet pour safety surfacing Safe for use		√				√	
5 Steppers & 2 Beams The equipment is installed in a safe manner onto grass. One bolt to replace. 1 stepper 1.38m to fence – should be 1.5m – low risk			√			√	
Kompan Spinning Dish ELE 00024 The equipment is installed in a safe manner onto wet pour safety surfacing. Safe for use		√				√	
Fahr Tangle Games Panel The equipment is installed in a safe manner onto wet pour safety surfacing. Safe for use		√				√	
Inspected by :J B Clark		Sheet - 2 of 9					



Annual Inspection








John Bedford Clark DipSm MIIRSM
3,Holly Terrace,
Balby,
Doncaster,
DN4 8RE
www.rynat.demon.co.uk

Site Address :- Hawesbury Play Area, High Street,
Hawkesbury, GL9 1AU

Grading Codes : **Date:** **Time : 15.00**
14 / 03 / 23

A) Satisfactory B) Monitor C) Work required to rectify D) Urgent Attention Required within 7 days

N 51 ° 34 ' 55 "
W 02 ° 19 ' 22 "

Equipment Inspected :-	Image	Grading Code				Conforms to BS EN 1176	
		A	B	C	D	Yes	No
Inclusive Roundabout The equipment is installed in a safe manner onto wet pour safety surfacing. Safe for use		√				√	
Kompan 2 Bay Swing – 2 flat , cradle & Tango Seats The equipment is installed in a safe manner onto wet pour safety surfacing. Safe for use		√				√	
Kompan Yellow Springer ELE400002 The equipment is installed in a safe manner onto wet pour safety surfacing. Safe for use		√				√	
Kompan Blazer ELE40021 The equipment is installed in a safe manner onto wet pour safety surfacing. Safe for use		√				√	
Inspected by :J B Clark		Sheet - 3 of 9					



Annual Inspection



John Bedford Clark DipSm MIIRSM
3, Holly Terrace,
Balby,
Doncaster,
DN4 8RE
www.rynat.demon.co.uk

Site Address :- Hawesbury Play Area, High Street,
Hawkesbury, GL9 1AU

Grading Codes : **Date:** **Time : 15.00**
14 / 03 / 23

A) Satisfactory B) Monitor C) Work required to rectify D) Urgent Attention Required within 7 days

N 51 ° 34 ' 55 "
W 02 ° 19 ' 22 "

Equipment Inspected :-	Image	Grading Code				Conforms to BS EN 1176	
		A	B	C	D	Yes	No
Fahr Abacus Games Panel The equipment is installed in a safe manner. Safe for use		√				√	
Fahr Tic Tac Toe Games Panel The equipment is installed in a safe manner. Safe for use		√				√	
Hags Unimini Unit The equipment is installed onto wet pour safety surfacing – finger entrapment to infi. Additional brake to fit on sand crane or remove				√		√	
Cableway The equipment is installed onto grass wear mats. Seat low – remove 100mm from the suspension chain to rectify. Safe for use upon completion.				√			√
Inspected by :J B Clark		Sheet - 4 of 9					



Annual Inspection








John Bedford Clark DipSm MIIRSM
3, Holly Terrace,
Balby,
Doncaster,
DN4 8RE
www.rynat.demon.co.uk

Site Address :- Hawesbury Play Area, High Street,
Hawkesbury, GL9 1AU

Grading Codes : **Date:** **Time : 15.00**
14 / 03 / 23

A) Satisfactory B) Monitor C) Work required to rectify D) Urgent Attention Required within 7 days

N 51 ° 34 ' 55 "
W 02 ° 19 ' 22 "

Equipment Inspected :-	Image	Grading Code				Conforms to BS EN 1176	
		A	B	C	D	Yes	No
Abra Monkey Bars The equipment is installed in a safe manner onto wet pour safety surfacing. Safe for use		√				√	
Kompan Spica GXY8014 The equipment is installed in a safe manner onto wet pour safety surfacing. Safe for use		√				√	
Abra Junior Unit The equipment is installed in a safe manner onto wet pour safety surfacing – couple of issues to monitor – see below			√			√	
Concrete Skate Area The equipment is installed in a safe manner onto wet pour safety surfacing. Signage in place. A couple of areas have blown in places on the concrete – monitor / repair Safe for use			√	√		N/A	
Inspected by :J B Clark			Sheet - 5 of 9				



Annual Inspection



John Bedford Clark DipSm MIIRSM
3, Holly Terrace,
Balby,
Doncaster,
DN4 8RE
www.rynat.demon.co.uk

Site Address :- Hawesbury Play Area, High Street,
Hawkesbury, GL9 1AU

Grading Codes : **Date:** **Time : 15.00**
14 / 03 / 23

A) Satisfactory B) Monitor C) Work required to rectify D) Urgent Attention Required within 7 days

N 51 ° 34 ' 55 "
W 02 ° 19 ' 22 "

Equipment Inspected :-	Image	Grading Code				Conforms to BS EN 1176	
		A	B	C	D	Yes	No
Teen Shelter The equipment is installed in a safe manner. Safe for use				√		N/A	
Potential trip point at gate entrance to address.				√		N/A	
1.38 to centre of stepper to fence – low risk			√			N/A	
Sand crane with one restrictor – add another couple or remove element				√		N/A	
Inspected by :J B Clark		Sheet - 6 of 9					



Annual Inspection



John Bedford Clark DipSm MIIRSM
3, Holly Terrace,
Balby,
Doncaster,
DN4 8RE
www.rynat.demon.co.uk

Site Address :- Hawesbury Play Area, High Street,
Hawkesbury, GL9 1AU

Grading Codes : **Date:** **Time : 15.00**
14 / 03 / 23

A) Satisfactory B) Monitor C) Work required to rectify D) Urgent Attention Required within 7 days

N 51 ° 34 ' 55 "
W 02 ° 19 ' 22 "

Equipment Inspected :-	Image	Grading Code				Conforms to BS EN 1176	
		A	B	C	D	Yes	No
It would be advantageous to extend pathways to impact areas to reduce wear				√		N/A	
Gap to infill on Hags toddler unit.				√		N/A	
Paint flaking on main swing frame.			√			N/A	
Cableway seat at 315mm , remove 100mm of suspension chain.				√		N/A	
Inspected by :J B Clark		Sheet - 7 of 9					





Annual Inspection



John Bedford Clark DipSm MIIRSM
3, Holly Terrace,
Balby,
Doncaster,
DN4 8RE
www.rynat.demon.co.uk

Site Address :- Hawesbury Play Area, High Street,
Hawkesbury, GL9 1AU

Grading Codes : **Date:** **Time : 15.00**
14 / 03 / 23

A) Satisfactory B) Monitor C) Work required to rectify D) Urgent Attention Required within 7 days

N 51 ° 34 ' 55 "
W 02 ° 19 ' 22 "

Equipment Inspected :-	Image	Grading Code				Conforms to BS EN 1176	
		A	B	C	D	Yes	No
There is some blown concrete on the skate park – not on the running surface – monitor / repair.				√		N/A	
Monitor potential trip point at 2 nd gate entrance due to grass mat.				√		N/A	
Skate signage in place.		√				N/A	
Unusual configuration on the attached swing – the unit is third party certificated by TUV			√			N/A	
Inspected by :J B Clark		Sheet - 8 of 9					





Annual Inspection



John Bedford Clark DipSm MIIRSM
 3, Holly Terrace,
 Balby,
 Doncaster,
 DN4 8RE
 www.rynat.demon.co.uk

Site Address :- Hawesbury Play Area, High Street,
 Hawkesbury, GL9 1AU

Grading Codes : **Date:** **Time : 15.00**
 14 / 03 / 23

A) Satisfactory B) Monitor C) Work required to rectify D) Urgent Attention Required within 7 days

N 51 ° 34 ' 55 "
 W 02 ° 19 ' 22 "

Equipment Inspected :-	Image	Grading Code				Conforms to BS EN 1176	
		A	B	C	D	Yes	No
Monitor gap on Junior unit for potential foot entrapment			√			N/A	
Monitor potential access to top beam of swing from unit platform			√			N/A	
Note:- A number of issues from the previous addressed and it is well maintained.							
Inspected by :J B Clark		Sheet - 9 of 9					

